



*Figure 1: Unit 405 ready for new sliding glass door installation*



*Figure 2: Unit 204 waterproofing the window sill and window will be reinstalled this week.*



*Figure 3: Bending/shearing and corrosion of aluminum track Unit 209; Unit will require new doors and windows at this bedroom location*



*Figure 4: Bending/shearing and corrosion of aluminum track Unit 209; Unit will require new doors and windows at this bedroom location*



*Figure 5: Unit 505 concrete placed back along the threshold on Friday, 7/18*



*Figure 6: Unit 509 concrete placed back along the threshold on Thursday, 7/17*